Oil Field Environmental Incident Summary

Incident: 20160316160600 Date/Time of Notice: 03/16/2016 16:06 Responsible Party: Oneok Rockies Midstream **ONEOK ROCKIES MIDSTREAM** Well Operator: Well Name: Rough Rider 2 Compressor station Field Name: Well File #: Date Incident: 3/15/2016 Time Incident: 17:00 Facility ID Number: **MCKENZIE Sec:** 13 **Qtr:** County: **Twp:** 145 **Rna:** 101 Location Description: Rough Rider 2 Compressor Station 13852 3rd Street SW Grassy Butte, ND 58634 Submitted By: Levi Weltikol Received By: Contact Person: Levi Weltikol 2700 Lincoln Ave SE Sidney, MT 59270 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Pipeline Leak Release Contained in Dike: Yes - On Facility Site Reported to NRC: No Spilled Units Recovered Units Followup **Units** Oil **Brine** Gallons Other 3 **Description of Other Released Contaminant: Natural Gas Condensate** Written Report Received: Clean Up Concluded:

Inspected:

Risk Evaluation: No immediate risks

Areal Extent:

Potential Environmental Impacts:

No environmental impacts associated with this release

Action Taken or Planned:

Pipeline was isolated. Boom laid down in case of rain. Will create Stockpiles of impacted soil, manage them and test to see if it needs to be removed from location.

Wastes Disposal Location: Impacted soil will be managed in stockpiles and tested to see if the soil

needs to be removed. If the soil needs to be removed it will go to a

certified landfill.

Agencies Involved:

Updates

Date: 3/16/2016 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a pipeline leak, impacted soils on the facility site. Further follow-up needed.

Date: 4/6/2016 Status: No Further Action Requested Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 2040. Contents of spill had been contained on compressor station by booms. No contaminants off site. No further action at this time.